



SPECIALIZED COATINGS AND PROTECTED ENVIRONMENTS

Thermal
Fire
Corrosion

Call Us for more information at 604-576-2212

PICTURE HISTORY OF RUST GRIP IN AUSTRALIA

The floor had machine cutting (lathe) oil dripping on the concrete for 25 years. To get the oil out we applied 5 coats of **SP INTERLOCK / INNERSEAL** ® to leach out the oil we then applied 2 coats of **RUST GRIP (NS)** ® and 2 coats of Aqua Pox to give us 2 test areas

This test area is over 5 years old the only wear and tear has been caused by the forklifts where the forks dragged over the floor surface to scar the surface.





Thermal
Fire
Corrosion

Call Us for more information at 604-576-2212

In the store area **RUST GRIP (NS)** ® Was applied over raw concrete 2 coats only and is now over 3 years old and shows no sign of wear





Thermal
Fire
Corrosion

Call Us for more information at 604-576-2212

No 538 Rust Grip is on the bottom and Aqua Pox on top 539





Thermal
Fire
Corrosion

Call Us for more information at 604-576-2212

Photo No 541F you see the heavy coffee stain and outlines where the stains have been removed after clean up. The **RUST GRIP (NS) ®** is as good as new. No corrosion. The reason I said no corrosion as I have been told that coffee is highly corrosive.



Project Pictures Courtesy of:
Tony Brady
SUPERIOR HI-TECH COATINGS