



Thermal  
Fire  
Corrosion

*Call Us for more information at 604-576-2212*

## LITTLE PARA RESERVOIR AUSTRALIA

**August 2007**

The walkway is to be inspected by engineers in the next week. The reason for doing the patches is to prove that this walkway can be refurbished without sand blasting using only Graffiti Cleaner and 2 coats of RUST GRIP ®.



**Before Prep**





Thermal  
Fire  
Corrosion

*Call Us for more information at 604-576-2212*

**Prepped using Graffiti Cleaner. In the cleaning process no lead-based paint or residue went into the water**





Thermal  
Fire  
Corrosion

*Call Us for more information at 604-576-2212*

**First coat RUST GRIP ®**





Thermal  
Fire  
Corrosion

*Call Us for more information at 604-576-2212*

**Second coat RUST GRIP®**

