

Rusting Roof

The problem in this instance was that the roof was leaking. In the first picture it can be seen where the roof had rusted right through. This area required a high build of about five coats of **SUPERTHERM**[®]. The fact that the coating also insulated was not a major consideration to this customer. When he was called as a reference however all he could talk about was that this was the coolest building in his facility. Oh and it didn't leak anymore.



The air conditioner shown in the bottom picture was running constantly when we first arrived. Before the first coat was completely applied, the air conditioner had stopped. We were so used to hearing it constantly in operation, that we were concerned we may have knocked a wire loose when we were cutting in around it. It did start a short cycle however which told us that it was fine. The reduced operation not only reduces the electrical consumption but also extends the life of the equipment

itself. SUPERTHERM® provides the added environmental benefit of a reduced HEAT ISLAND EFFECT.