


vw bug

november

2009

SUPERTHERM ® over RUST GRIP ®

Here she is all stripped down. Glass, carpet, headliner, dash.. all gone. Now just some major cleanup before we start trying to put the new stuff in.







RUST GRIP® Primer coat





SUPERTERM® Top coat

I put the SUPERTERM® coating on the Bug today. Man! This thing looks like it is ceramic coated inside. Even with no panels, closing the doors feel very solid. I did all the pan and inside surfaces with heavy coats on the rear because of the engine. Also did inside each of the door and rear side panels, as well as the inside of the roof. I am very excited to see how this thing sounds once we get it all put back together.





Photos courtesy [Songman](#)