


**Scandic Hotel
Antwerp**

Received in 2007

SUPERTHERM® and Primer **RUSTGRIP**®



Situation at Scandic Hotel Antwerp: damaged airco ducts on top of roof, due to bird vandalism.



Corrosion after condensation because of damaged ARMAFLEX insulation.






Total area to be done: 800 m²





Mastic Sealing Tape over loose seams




Rubber like top coat, to be sanded to make Rust Grip able to penetrate into the pores

After sanding the surface.



After filling bird picked holes with PU foam





Super
Therm
Finish

Primer
Rust Grip

Initial temperature
at outside cooled
pipes during sunny
day.
Ambient
temperature 26°C





Surface temperature after
Super Therm application
25°C.









Project Pictures Courtesy of: Stefan Rutten

Superior Products Europe N.V.

Kampweg 123

2990 Wuustwezel Belgium

mob: 32.(0)475.32.64.73

tel: 32.(0)3 690 02 40

fax: 32.(0)3 690 02 41

www.specoating.com

info@specoating.com